



## ELEVATION DETAIL - EAVES BLOCKING AT DOUBLE STUD WALL, MASONRY VENEER EXTERNAL WALL RD0021A



**Researcher:**  
Timber Development Association (NSW)

© 2014 Forest and Wood  
Products Australia Limited.  
All rights reserved.

These materials are published under the  
brand WoodSolutions by FWPA.

### IMPORTANT NOTICE

The work IN ITS ORIGINAL STATE is copyright and protected under the terms of the Copyright Act 1968.

Permission is granted to reproduce or modify the contents of this document in whole or in part, provided all reference to FWPA, WoodSolutions & Timber Development Association (NSW) is REMOVED.

Forest and Wood Products Australia Limited and WoodSolutions Australia and all persons associated with them (FWPA) as well as any other contributors make no representations or give any warranty regarding the use, suitability, validity, accuracy, completeness, currency or reliability of the information, including any opinion or advice, contained in this document.

To the maximum extent permitted by law, FWPA excludes all liability in contract, tort (including negligence), or otherwise for any injury, loss or damage whatsoever (whether direct, indirect, special or consequential) arising out of or in connection with use or reliance on this document.

### DETAIL REFERENCE NO.

# RD0021A

### REVISION STATUS

REV A / 01-06-2014 / MS  
Original release.

### SCALE

1:10 ON A4 SHEET